

IBM 5x86C Microprocessor Support Summary



Solution Pak

Motherboard Manufacturers:

Company: ELITEGROUP Computer Systems, Inc. (ECS)
Product: ECS UM8881 A10
Chipset: UMC 8881
BIOS: Phoenix
Contacts: (510-226-7333)

Company: Chicony
Product: CH471B
Chipset: SIS 85C471
BIOS: Award
Contacts: (714-380-0928)

Company: First International Computer, Inc. (FIC)
Product: 486-PVT
Chipset: VIA VT82C496G
BIOS: Award
Contacts: (510-252-7777)

Company: Alaris
Product: Cyclone
Chipset: PicoPower Redwood
BIOS: MR BIOS
Contacts: (510-770-5700)

*****Motherboard information is provided by the companies listed above and is subject to change without notice. Please have the system or board manufacturer contact the vendors listed above directly for updates. The customer is solely responsible for selection of a Board, Chipset, or BIOS company.**

IBM 5x86C Microprocessor Support Summary

Solution Pak

Chipset Manufacturers:

Company: SIS Corp.
Product: SIS 471B-E, 496/497
BIOS: Phoenix, Award, AMI, MRBIOS (471)
Contacts: Earl Porter, Sales Manager (408-774-4547)

Company: ALI
Product: M1429G, M1439, M1489/87
BIOS: Phoenix, Award,
Contacts: Lolin Dino, US Sales (408-764-0644)

Company: VIA Technologies
Product: VT82C486A, VT82C496G
BIOS: Award, Phoenix, AMI, MR BIOS (VT82C496G)
Contacts: Dick Renne, Strategic Planning Manager (510-683-3316)

Company: Opti Inc.
Product: 802GP, 895
BIOS: Phoenix, Award, AMI, MR BIOS (802GP)
Contacts: Prem Talreja, Director of Marketing (408-980-8178)

Company: ACC Microelectronics
Product: 2066NT, 2178A, 2048, 2087
BIOS: Phoenix, Award
Contacts: Grace Louh, Sales (408-980-0622)

*****Chipset information is provided by the companies listed above and is subject to change without notice. Please have the system or board manufacturer contact the vendors listed above directly for updates. The customer is solely responsible for selection of a Board, Chipset, or BIOS company.**

IBM 5x86C Microprocessor Support Summary

Solution Pak

BIOS Manufacturers:

- Company:** Phoenix *(Core has support, have Mfg. call for customized)*
Chipsets : SIS (471, 496/497), ALI (M1429G), VIA(VT82C486A, VT82C496G), Opti(82C802GP, 82C895), UMC (498, 880), PicoPower (Redwood, Fir), ACC (2178A), C&T (4041), Symphony (SL82C491)
Contacts: Jerry Ward, Product Manager (714-440-8017)
- Company:** Award *(Core has support, have Mfg. call for customized)*
Chipsets : SIS (471, 496/497), ALI (M1429G, M1439), VIA(VT82C486A, VT82C496G), Opti (82C802GP, 82C895), UMC (498, 880), PicoPower (Redwood, Fir), ACC (2178A), C&T (4041)
Contacts: Jeffery Flink, Director of Marketing (415-968-4433)
Robert Lee, Sales Manager 011-886-2555-0880
Axel Schafer, Sales Manager 011-49-89-575750
- Company:** MR BIOS *(Core has support, have Mfg. call for customized)*
Chipsets : Opti (82C802GP), SIS (471), UMC (880), PicoPower (Redwood), VIA (VT82C496G)
Contacts: Michael Meisner, President (408-727-6991)
- Company:** SystemSoft *(Core has support, have Mfg. call for customized)*
Chipsets : Support chipsets from Intel, VLSI, Opti, ACC, PicoPower, UMC, SIS, VIA
Contacts: Stephen J. Gentile, Product Marketing Manager (508-647-2848)
- Company:** AMI *(Core has support, have Mfg. call for customized)*
Chipsets : SIS (471, 496/497), ALI(M1429G, M1439), VIA(VT82C486A, VT82C496G), Opti (82C802GP, 82C895), UMC (498, 880), PicoPower (Redwood, Fir)
Contacts: David Maddox, Director of Sales (404-246-8612)

*****BIOS information is provided by the companies listed above and is subject to change without notice. Please have the system or board manufacturer contact the vendors listed above directly for updates. The customer is solely responsible for selection of a Board, Chipset, or BIOS company.**

IBM 5x86C Microprocessor Support Summary

Solution Pak

Information contained in this document was provided by the vendors listed above and is subject to change without notice. The vendors should be contacted directly for updates. The customer is solely responsible for the selection of a board, chipset, or BIOS vendor.

The vendors listed above are not agents or representatives of IBM and are not authorized to make any representations or warranties whatsoever on behalf of IBM. IBM makes no representations or warranties regarding the compatibility of the vendors products, including such products listed above, with any IBM products.

THE INFORMATION PROVIDED IN THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND NO WARRANTIES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE ARE PROVIDED HEREIN.